



ARDON®
WORKWEAR
& OUTDOOR

ARDON 3L® ULTRITE® GO!

MEN'S 3L JACKET



TECHNICAL DATA SHEET

COMFORT FIT



RECYCLED MATERIAL



WATERPROOF 20 000



VENTILATION



BREATHABLE 20 000



3D SILHOUETTE



WINDPROOF



DRY AIR



WATERPROOF ZIPPERS



ARDON®
WORKWEAR
& OUTDOOR

ARDON 3L® ULTRITE® GO!

MEN'S 3L JACKET

ITEM CODE H6247 (orange)
 H6248 (khaki)
 H6249 (dark blue)
 H6246 (black)

MATERIAL
COARSE MATERIAL 100 % recycled polyester

GRAMMAGE 188 g/m²

SIZE S – 3XL
 H6246 S – 4XL

DESCRIPTION

A durable and functional men's jacket designed for tough conditions. With its three-layer design and taped inner seams, it offers reliable protection against rain and wind. The waterproof zippers provide the best possible protection from moisture, while underarm ventilation zippers ensure effective ventilation during heavy exertion. The jacket has an adjustable hood. The bottom hem enables easy adjustment of the jacket's bottom width, 1 inner zipper pocket, 2 side zipper pockets and 2 chest zipper pockets provide plenty of space to store all your essentials. The jacket is a great choice for leisure and outdoor activities and challenging terrain.

This product is not PPE (personal protective equipment); therefore, it is not subject to certification and cannot be CE-marked.

TECHNICAL DATA SHEET



ARDON®
WORKWEAR
& OUTDOOR

NUMBER OF PIECES IN CARTON	10 pcs
CARTON WEIGHT	12 kg
CARTON SIZE	0,102 m ³
UNIT PACKAGING	of 1 pc

The service life depends on the degree of use and the rate of wear in the given conditions. Improper storage conditions, improper maintenance and care shorten the service life. The warranty period is 24 months. In no case should the warranty period be confused with the service life of the product. With intensive use, the service life may be shorter than the warranty provided.

The product does not contain any substances in concentrations that are known or suspected of adversely affecting the hygiene or health of the user. However, skin irritation is not excluded for sensitive people, in which case do not continue to wear clothing. Avoid fire and sources of intense heat.

No accessories or spare parts are intended for these garments. If clothing is not in use, it is recommended to store it in a dry and well-ventilated area away from direct sunlight. Transport preferably in the original packaging, protect from moisture and extreme temperatures. Dispose of ecologically after use.

TECHNICAL DATA SHEET



ARDON®
WORKWEAR
& OUTDOOR

TECHNICAL DATA SHEET

